


An Engineered Anchored Resilient System.

- ❑ DIN/EN-compliant system
- ❑ Flexible performance options
- ❑ Outstanding substrate air flow
- ❑ Consistent ball rebound
- ❑ Engineered sleeper design



- ❑ Horner MFMA Maple
- ❑ Modified steel drive pins
- ❑ Rated panel
- ❑ Engineered laminated sleeper
- ❑ ECO or SAFE pad options



LEED

Options Available

Traditional gymnasiums, field houses and auxiliary gyms, heavy-use facilities and competition arenas.

PERFORMANCE

Meets or exceeds DIN18032-Part II / EN 1490-2006

PERFORMANCE CHARACTERISTICS

| | |
|--|---|
| Shock Absorption | ✓ |
| Vertical Deflection | ✓ |
| Area of Deflection | ✓ |
| Ball Bounce | ✓ |
| Surface Friction (Coefficient of Friction/Sliding Coefficient) | ✓ |
| Rolling Load | ✓ |

SPECIFICATIONS

System Thickness*/Pad Options

□ 25/32" MFMA Horner Maple:

2 1/2" Floor using 7/16" SAFE or ECO pad

2 3/4" Floor using 3/4" SAFE pad

□ 33/32 MFMA Horner Maple: Add 1/4"

*System thickness is equivalent to slab depression for new facilities.

MATERIALS

Option: Specify Horner LongLife™ Maple

Subfloor: Rated sheathing

Modified steel drive pin anchors

Floating option

SAFE or ECO pad options

Vapor retarder

GREEN/LEED OPTIONS

FSC Maple Flooring MRC 7

FSC Subfloor Components MRC 7 Exemplary Performance

Recycled ECO Pads MRC 4.1 & MRC 4.2


INSTALLATION REFERENCES

Mulkiteo YMCA, Mulkiteo, WA

Formen/Reynaud C.C., Lake Charles, LA

Jasper Middle School, Jasper, IN

Franklin High School, Livonia, MI



SPECIFY



For extended wear life, choose **Long Life™**. Horner's **Long Life™** flooring is 25/32" northern hard maple with the same wear depth as 33/32" flooring. **Long Life™** provides the ecological, cost savings and availability benefits of a 25/32" floor, with extended wear life. More re-sands, stronger system and economical. Why not value engineer?

HORNER FLOORING is the leading manufacturer of athletic flooring systems used in high-school gyms, college and professional arenas, and public and private training facilities.



Cert no. SW-COC-000220
© 1996 Forest Stewardship Council



Please contact us regarding our extended maintenance warranty options.

Horner Flooring Company's policy is to continuously improve its line of products. Therefore, Horner Flooring Company reserves the right to change, modify or discontinue models, specifications and accessories of all products at any time without notice or obligation to any purchaser.

HORNER FLOORING COMPANY, INC.
800.380.0119 / www.hornerflooring.com

P.O. Box 380, 23400 Hellman Avenue, Dollar Bay, MI 49922
P: 906.482.1180 / F: 906.482.6115 / info@hornerflooring.com